



Ministry of Finance

Ameenee Magu, Male', Republic of Maldives

Telephone:1617, (960) 334 9296

ދިވެހިރާއްޖޭގެ ފަރާތުން
މިނިސްޓްރީ އޮފް ފައިނަންސް
މާލެ، ދިވެހިރާއްޖެ

Clarification 1

1 ވަނަ ބަޔާން

ނަންބަރު No:	TES/2021/W-092	
ފޮތް ނަންބަރު Project:	Construction of Th. Dhiyamigili Mosque.	
އުދުހުކުރު ދުވަހު Issued Date	14 th July 2021	
ސަފުހާ ގެ ޖަދުވަލު No. of Pages: -1	ބީއޯ: -00	ޑްރޯއިންގ: -00

މި ބަޔާނު ހިމާނުވާ ބަޔާން ދިނުމުގެ ތެރޭގައި މި ބަޔާނު ހިމާނުވާ ބަޔާން ދިނުމުގެ ތެރޭގައި މި ބަޔާނު ހިމާނުވާ ބަޔާން ދިނުމުގެ ތެރޭގައި

	Question	Clarification
1	Please be informed that 1.6mm 90mm Steel tie to be used as ringbars(Mentioned in the BOQ) hence the ring size shown in drawings is R6. Please clarify?	Bill no. 3 Concrete, Foundation Pads F1, F2 and F3 has 12mm Rebars T12@100 c/c BW(B) but no rings. 1.6mm steel ties are not rings. Foundation beams FB1 has 6mm rings R6@150 c/c and TB1 has 6mm rings R6@100 c/c as shown in drawings and BOQ template.
2	Please clarify the foundation Depth of the Mosque?	Foundation depth minimum in regulation shall be 1200mm. The mosque foundation is at that depth, But the Minaret foundation must go beyond that as per engineer as it requires that depth. So ask the contractor to follow the drawings.

ނަންބަރު

Name: Fathimath Rishfa Ahmed

ސަފުހާ

Signature:

