تبسما مندازحمن إزحيهم



Ministry of Finance and Treasury

Ameenee Magu, Male', Republic of Maldives Telephone: (960) 334 9266, Fax: (960) 332 0706 وِبرِ اللهِ مِنْ رِبْرُدُ مِنْ عُرْدُهِ دُوِيرِدُ ذُهُ اللهِ مِنْ رِمْدُغُ

AMENDMENT 1

1 00 100 66

No:	TES/2017/W-13	
Project:	Health Centre Extension (Finishing work) – Gdh.Faresmaathoda	
Issued Date	24 th April 2017, Monday	
352 5554 No. of Pages: -01	3.5.2. 2.3.3.2 Boq: -00 Drawings: -00	

وَ الرَّوْدُورِ وَ مَا وَمُورِدُ مِنْ مُورِدُ مِنْ مُورِدُ مُعْرِدُ مُنْ الْمُرْدُورُورُ عَرِيْ وَمُرَوْرُونُ مُؤْمِرُونُ مُؤمِرُونُ مُؤمِرُونُ مُؤمِرُونُ مِنْ اللَّهِ اللَّهُ اللّهُ اللَّهُ اللَّهِ اللَّهُ اللَّهُ اللَّهُ اللَّهُ اللَّهُ اللَّهُ اللَّهُ اللَّاللَّهُ اللَّهُ اللَّالِي اللَّهُ اللَّاللَّالِيلَالِي اللَّهُ اللَّهُ اللَّالِيلَاللَّالِيلُولِ الللَّال

- > Clarifications are attached to this Amendment.
- ➤ Please include the adjustment prices in addition and omission bill: Tenderer's Adjustments.

The <u>Bid Opening</u> for the project has been postponed to <u>Wednesday</u>, 3rd <u>May 2017</u>, <u>11:00hrs</u> at National Tender and Project Monitoring section of Ministry of Finance and Treasury (5th floor, Treasury building)

		// //	3	16	(2)
4.4.	2 <u>*</u>			· ARC.	130
Name: Ahmed Mujuthaba	Signature:	W	(RY
		D - 1	Λ		*
			3	25 75	8
			(e.	Ro Maldi	/
			1	conpublic of	

Gdh.Faresmaathoda Health Centre Extension Finishing Works

Queries/Clarifications Required

1.Bill No:3, Concrete

3.1.2.Ground Floor

Thickness of Ground Floor Slab is mentioned as 100mm in BOQ and it is shown as 75mm thick in drawing (Refer Cross section X-X). Please clarify it.

Ground slab thick ness is 100mm thick.

2.Bill No:6,Doors and Windows

6.2.Door/Windows Units

(i).In BOQ Door D2 is noted as Aluminum Framed Door but in Door and Window Schedule it is shown as Timber Framed Door.

D2 is a Timber door.

(ii). No details regarding the Door to be provided in the Laboratory Room.

Size of laboratory door (sample collection to laboratory room) is D3

(iii). As per BOQ the Timber Framed Doors D4 is mentioned as 3 nos. In Floor Plan it is shown only 2 nos.

Please follow the drawings.

(iv). As per BOQ Door D5 is given as 2 nos but in door & window schedule drawing, no D5 details is mentioned.

No D5 door in the Drawing, No need to quote this item.

(v). In Floor Plan the number of Windows W1 is 12 nos. But in BOQ, it is given as 14nos.

Please follow the drawings.

(vi).In BOQ, Window W3 is 2 nos. No details in both Floor plan and also in door & window schedule drawing.

Please follow the drawings.

6.4. Window Curtains

In Floor Plan the number of Windows W1 is 12 nos. But in BOQ, it is given as 14nos.

Please follow the drawings.

6.5. Counters

No details regarding Registration Counter and Nurse Station Counter.

Please follow the BOQ item no 6.1 (1) and (2). Contractor to quote price for designing and fabrication of counters.

6.6. Partition Works

100mm thick is mentioned in BOQ but 75mm thick shown in drawing.

Partition thickness is 100mm.

3.Bill No:10, Electrical Installations

10.2. Mains Connections

Distance of Main cable from Main Electricity to the site.

Contractor has to check nearest distribution board and cable length from site.

10.5. Lighting/Fan

No Fan details given in BOQ. But fan is shown in the Electrical Layout. If Fans to be provided then the BOQ has to be revised. Need Details.

Please follow the drawings.

