

ANNEX - 02

PROGRESS OF WORK FOR CATEGORIZED STAGES - REMEDIAL AND COMPLETION OF 100 HOUSING UNITS

SUMMARY OF WORKS DONE IN HDH.NOLHIVARANFARU

DESCRIPTION OF WORKS											
Concrete works											
Foundation	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
Columns	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
Roof beams	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
Lintel beams	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
Floor Screed	100%	100%	100%		100%	100%	100%	100%	100%	100%	100%
Block works											
Exterior Masonry works	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
Interior Masonry works	100%	100%	100%		100%		100%	100%		100%	100%
Plastering											
Exterior Plastering	100%	85%					85%	85%	85%	100%	100%
Interior Plastering	100%	85%						85%		100%	100%
Roofing Works											
Roofing frame	100%			100%	100%		100%	100%	100%	100%	100%
Rock wool installation	100%			100%	100%		100%	100%	100%	100%	100%
Roofing sheet installation	100%			100%	100%		100%	100%	100%	100%	100%
Gutter and downpipe				50%	50%		50%			50%	50%
Finishing Works											
Interior Painting										100%	100%
Exterior Painting	100%									100%	100%
Ceiling works (Interior & Exterior)	70%									100%	100%
Tiling	85%									70%	70%
Doors										30%	15%
Windows										80%	
Utilities											
Plumbing	80%									80%	80%
Electrical wiring	80%							20%		100%	100%
Installation of Electrical fittings											50%
Installation of Sanitary ware											80%
Well	100%										

CATEGORY	QTY
ORANGE	4
RED	6
MAGENTA	18
WHITE	6
GREY	17
CYAN	8
GREEN	13
PURPLE	13
BLUE	13
BLACK	1
DARK GREEN	1
TOTAL	100